



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Sivilian Director

Representatives Present During the Inspection:

OGM Karl Houskeeper

Inspection Report

Permit Number:	C0070019	
Inspection Type:	PARTIAL	
Inspection Date:	Monday, November 22, 2010	
Start Date/Time:	11/22/2010 8:00:00 AM	
End Date/Time:	11/22/2010 11:30:00 AM	
Last Inspection:	Tuesday, October 05, 2010	

Inspector: Karl Houskeeper,

Weather: Overcast, Temp. 25 Deg. F.
InspectionID Report Number: 2562

Types of Operations

Accepted by: jhelfric 12/1/2010

Permitee: ANDALEX RESOURCES INC Operator: ANDALEX RESOURCES INC

Site: CENTENNIAL MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Cur	rent	Acreages

6,528.83	Total Permitted		
47.19	Total Disturbed		
	Phase I		
	Phase II		
	Phase III		

Mineral Ownership

✓ Federal
✓ Underground

✓ State
□ Surface

□ County
□ Loadout

✓ Fee
□ Processing

□ Other
□ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Checked in at the UtahAmerican Main Office located at the West Ridge Mine prior to conducting the inspection. Conducted the inspection unattended.

Light blanket of snow at the Centennial Mine site.

Inspector's Signature:

Inspector ID Number: 49

Karl Houskeeper,

Date

Monday, November 22 2010

DIL, GAS & MINING

Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Monday, November 22, 2010

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches	✓	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓	✓		
8.	Noncoal Waste	V			
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Inspection Continuation Sheet

Permit Number: C0070019 Inspection Type: PARTIAL

Inspection Date: Monday, November 22, 2010

Page 3 of 3

2. Signs and Markers

Mine identification sign is located at the point of public access to the permit area. The sign has the requied information.

3. Topsoil

Topsoil sign at topsoil pile located by uppermost storage yard was down. Put sign back up where it is now visible. This sign should be monitored and may need to be secured tighter.